

Reference	Date/Time	Location	Runway	F/W Movements	Total Movements	Complaint	Action
FW12/2026	15/08/26 1555hrs	RH1 SPD	07R	111	132	Departing aircraft flew over location causing horse to bolt.	Complainant resides within the ATZ adjacent to the climb-out and crosswind of Rwy07. Aircraft are required to fly south and east of this location. The aircraft was identified as a PA28 operated by a by Redhill Aviation. Email sent to operator requiring the pilot to be re-briefed. Complainant updated via email